

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

HB1021
NE
> 1
1.332 mi.
7032 ft.

JAKE ELMANN RES.
1029 CRAWFORD AVE
BROOKLYN, NY

NY Spills S106382895
N/A

Site 1 of 2 in cluster HB

Relative:
Higher

Actual:
10 ft.

SPILLS:

Name: JAKE ELMANN RES.
Address: 1029 CRAWFORD AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0312803 / 2004-03-05
Facility ID: 0312803
Facility Type: ER
DER Facility ID: 151670
Site ID: 180828
DEC Region: 2
Spill Cause: Unknown
Spill Class: C3
SWIS: 2401
Spill Date: 2004-02-17
Investigator: CESA WYER
Referred To: Not reported
Reported to Dept: 2004-02-18
CID: 406
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Citizen
Cleanup Ceased: Not reported
Cleanup Meets Std: False

Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2004-02-18
Spill Record Last Update: 2004-03-17
Spiller Name: JAKE ELMANN
Spiller Company: JAKE ELMANN RES.
Spiller Address: 1029 CRAWFORD AVE.
Spiller Company: 001
Contact Name: JAKE ELMANN
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAWYER 3/5/04 - Sawyer - Told Mr. Elmann to talked to the DEP for guidance and help from clogged sewer pipes. He was going to have a sewer evaluation done for the tributaries in his area. This concluded our involvement. Closed."

Remarks: "Raw Sewage came from the sewer and came out of the toilet filling the basement with both sewage and water. Plumber came today fixing the [plumbing. In the process of cleaning up. Putting material into buckets not sure of what to use as absorbent material. "

All Materials:

Site ID: 180828
Operable Unit ID: 880078
Operable Unit: 01
Material ID: 497983
Material Code: 0062A
Material Name: raw sewage
Case No.: Not reported
Material FA: Other
Quantity: .00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Units: L
Recovered: .00
Oxygenate: Not reported